



F-1500 MOV Fog Machine

User Manual




PLEASE READ MANUAL THOROUGHLY BEFORE OPERATING MACHINE

TECH SUPPORT: (256) 229-5551

SKILL INFORMATION:

Heat Up Time	10 Mins
DMX 512	Electronic Thermoswitch
Tank Capacity:	2L
Approximate Fog Projection:	12 Meters
The Angle of Smoking:	1800
Weight:	14 KG / 30 LBS
Output:	20,000 Cubic Feet/Minute
Voltage:	AC 110V; 220-250V; 50/60Hz
Power:	1300 W
Size:	44 x 35 x 23 CM / 17" x 14" x 9"



OPERATING THE MACHINE WITH LCD CONTROLLER:

1. Connect the power line to the power socket with Earth line. Turn the switch to 'ON" and the machine will begin heating. The SCREEN will show "Ready to Fazer" when the machine is finished Heating.
2. Press the MANUAL button and use the up & down arrows (↑ ↓) to adjust the working angle.
3. Press the VOLUME button and use the up & down arrows (↑ ↓) to adjust the fog output.

OPERATING THE MACHINE WITH DMX512 CONTROLLER:

1. Connect the machine to the DMX512 controller. [The DMX512 has two channels— (1) for adjusting the working angle and (1) for adjusting the fog output).
2. Connect the power line to the power socket with the Earth line. Turn the switch to “ON” and the machine will begin heating. The SCREEN will show “Ready to Fazer” when the machine is finished heating.
3. Machine Settings: The DMX address is 1. The DMX controller channels are 1 and 4. Channel 1 is to adjust the fog output. Channel 4 is to adjust the working angle

ATTENTION/CAUTION:

1. Please operate this machine carefully and abide by all notices regarding safety and operation for the machine to avoid electrical shock and produce high-quality special effects.
2. Keep the machine clean.
3. Best used indoors.
4. Do not incline the machine or place upside down. Ensure the machine is in its upright horizontal position.
5. Power machine off after use.
6. This machine is not waterproof. Do not run if humidity, water, or liquids get inside the machine. Power off and contact Global Special Effects for support. Tech Support: (256) 229-5551.
7. Do not attempt to perform your own maintenance or repairs as it may damage the machine and void the warranty. Power off and contact Global Special Effects for any maintenance or repairs you may need. Tech Support: (256) 229-5551.
8. Do not operate the machine with a low or empty fluid tank. Operating the machine without fluid will cause damage to the machine and void the warranty.
9. If your machine isn't producing fog or the plum is making noises, please perform the following steps: (1) Power off the machine; (2) Check fluid levels; (3) Check the fuse; (4) Check the connector of the remote console; (5) Check the power plug. If the problem cannot be solved by checking these parts, please contact Global Special Effects for support. Tech Support: (256) 229-5551.
10. Do not consume or ingest fog fluid. In case of consumption, contact your medical provider immediately.
11. If fog fluid comes in direct contact with skin or eyes, rinse with clean cold water.

TO AVOID FIRE:

1. This machine is to be operated by adults only.
2. Keep out of reach of children.
3. Do not spray directly at others and keep away from open flame.
4. The fog can be produced at a high temperature, so allow at least 36" of space between the machine and any other material or objects affected by temperature.
5. Place the machine in a drafty location and do not cover the holes for the best results. Keep a distance of at least 8" between the machine and nearby things.
6. Keep flammable materials at least 9 ft. away from the machine.

TO AVOID EXPLOSION:

1. Do not add any flammable liquids such as oil, gas, perfume, etc. into the fog machine.
2. Pay attention to all notices and instructions for the machine.
3. Operate the machine with fluid from Global Special Effects only.
4. Ensure the machine is running with enough fluid. Operating the machine with little to no fluid will cause damage to the machine and void the warranty.
5. Empty all fluid from the machine before transportation.

BEFORE YOU START:

1. Open the package and confirm all the necessary pieces are included. If you believe you are missing an item, please contact Global Special Effects for support. Tech Support: (256) 229-5551.
2. Inspect the appearance of the machine and power line to ensure there isn't any damage from shipping. If you believe your machine has been damaged during shipping, do not use the machine and contact Global Special Effects for support. Tech Support: (256) 229-5551.

INSTALLATION:

1. Open box and remove all packing materials, especially around the spray nozzle.
2. Place the machine in a horizontal position and open the fluid can.

3. Add Global Special Effects Fog Fluid to the fluid can and screw cover back on.
[Using fluid other than Global Special Effects will void the warranty and may cause damage to the machine.]
4. Plug the remote console in the socket located on the back of the machine.

CLEANING:

1. Do not allow dust and dirt to accumulate on the fog machine.
2. Cleaning your fog machine on a regular basis and before & after use will extend the life of your machine.

1-YEAR LIMITED WARRANTY

Global Special Effects provides a 1-year limited warranty for the F-1500 MOV Fog Machine from any manufacturing defects. Any misuse, abuse or negligence automatically voids this warranty. Using any fluids/materials other than Global Special Effects fluids automatically voids this warranty. Global Special Effects is not responsible for loss of income, labor, or business as a result of a F-1500 MOV Fog Machine malfunction. Global Special Effects is not responsible for physical damage or scratching after shipping from Global Special Effects manufacturing facilities. Repairs are at the sole discretion of Global Special Effects. All shipping and handling costs are excluded from this warranty. Contact (256) 229-5551 for customer service.



(256) 229-5551

www.GlobalSpecialEffects.com

11054 County Road 71, Lexington, AL 35648